

Contents

1 Accuracy – interchangeability – gauging

Conditions and synthesis of accuracy – Interchangeability and limit systems – BS system – Selective assembly gauging – Limit gauges – Indicating gauges – Special and first operation gauges

1

2 Measurement and precision work

Slip gauges – Comparator – Vernier height gauge – Marking out – Vernier micrometer – Examples of measurement – Sine bar – Angular testing – Use of rollers – Tapers – Projection

31

3 Machine tools

Standard and special purpose machines – Elements of construction – Bed – Spindle – Speeds – Work holding – Tool attachment – Feeding – Tool lubrication – Rigidity – Surface formation – Machine-tool accuracy – Alignments – Testing

69

4 Further work on the lathe

Promotion of accuracy – Examples – Taper turning attachment – Effect of tool height – Eccentric turning – Form turning – Collet chuck – Multi-start screws – Leadscrew accuracy – Quantity production methods – Square tool box – Leaving for grinding – Boring on saddle – Button boring – Slotting

116

5 Milling

Horizontal machine – Cutter support – Types of cutters – Teeth – Helical – Relieved – End and face mills – Rotation – Feed – Choice of cutter and set-up – Care of machine – Examples of plain milling – Fixtures – Slotting attachment

151

6 Milling (continued)	
Dividing head – Simple and angular indexing – Work holding – Alignment – Examples of work – Settings for cutting side, taper and clutch teeth – Gear cutting – Rack cutting attachment – Vertical milling – Machine – Vertical head – Equipment for vertical work – Examples – Jig boring on vertical machine	190
7 Shaping, planing and slotting	
Hydraulic shaper – Drive – Circuit diagrams – Examples of work – Use of dividing head – Planer – Table drive – Electric control – Tools and support – Work setting – Examples – Slotting machine – Operating motion – Slotter tools – Examples of work	227
8 Drilling and boring	
Standard and special drills – Chucks – Quick change holders – Machines – Vertical – Radial – Sensitive – General purpose drilling – Examples – Drill jigs – Design – Facing – Counterboring – Deep drilling – Horizontal boring – Tools, cutters and bars – Facing – Setting up – Examples – Boring fixtures – Vertical boring mill	265
9 Grinding	
Scope of process – Wheel – Abrasive, artificial and natural – Manufacture – Bond – Types of bond – Grit and grade – Wheel manufacture – Structure – Shape – Classification – Selection – Wheel mounting – Truing and dressing – Speeds – Faults – Hand grinding – Tools – Lathe grinding attachments – Cylindrical grinding – Speed and feed – Machine and its construction – Steadies – Vibration – Operation of machine – Taper grinding	304
10 Grinding (continued)	
Internal grinding – Machine – Internal spindles – Wheels – Examples of work – Surface grinding – Methods – Disc and ring wheels – Magnetic chuck – Types of surface machines – Hydraulic driving – Examples of surface grinding – Tool and cutter grinder – Setting and sharpening various cutters – Cutting off by abrasive wheel – Oilstones – Grinding wheel recommendations	345

Appendix

1 Metric/English conversion tables	386
2 Brown and Sharpe tapers	388
3 ISO limit system. Details of holes and shafts	390
4 ISO limit system. Selected hole and shaft relationships	392
5 British Standard specifications of interest to the workshop engineer	393
Index	397